

In the Drawings:

Replacement sheets for Figures 4 and 5 are included herewith. After review of the instant application it is apparent that lead line "80" (seal) was misapplied in some of the initial drawings. The lead line has been corrected in the replacement Figures 4 and 5. Applicant's attorney respectfully requests the Examiner enter these drawings.





FIG. 3




FIG. 4

Approved PTT



apparatus

3/5




FIG. 5




FIG. 6